Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080136-3

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11344

RECEIVED FROM

PLANT #

DATE REC'D 2-25-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	0	17	0	21	3	62			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
11	733311 Pin Shuffle Roller	11 ✓		
	IPS #A003303			

RECEIVED BY HMC-1068 Barcelos

INSPECTED BY Dwa DATE 2/28/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11361

RECEIVED FROM

PLANT #

DATE REC'D 2-25-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	29	0	22					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
15	730125-13 Relay	15 ✓		
	IPS #A003277			

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080136-3

RECEIVED BY HMC-1068 Barcelos

INSPECTED BY Dwa DATE 2/26/57

REJECTS RETURNED ON SHIP. MEMO NO.